



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

September 1, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Special Report 83-046/1 -
Update Report - Fire Door
OC103 Inoperable
AECM-83/0530

This is an update to a previous report submitted on June 20, 1983. The condition for which the report was submitted occurred on May 15, 1983, when during surveillance testing, fire door OC103 was found to be damaged and in a constant alarm state. The door latch mechanism was damaged as a result of heavy use. The door was not repaired within the time limit of the action statement of Technical Specification 3.7.7, therefore, the report was submitted as a Special Report pursuant to Technical Specification 6.9.2.

An hourly fire watch was conducted and maintained until the door was restored to operability on August 23, 1983. This condition had no affect on the health and safety of the public and did not constitute a threat to plant safety. This is a final report.

Yours truly,

L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap

cc: (See Next Page)

8309120365 830901
PDR ADOCK 05000416
S PDR

Member Middle South Utilities System

OFFICIAL COPY

Te 22
1/0

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. T. B. Conner
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555