



# MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

September 1, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Special Report 83-073/0 - Fire  
Barriers in Control Room  
Not Installed  
AECM-83/0537

On July 26, 1983, during a special inspection of fire-rated assemblies, it was discovered that fire barriers in the Control Room were not installed at locations U714 L067/68-LA38 and U717 L079/80-LA11. A fire watch was established in accordance with Technical Specification 3.7.7 until the barriers were installed on August 27, 1983.

This is reported as a Special Report pursuant to Technical Specification 6.9.2 since the seven (7) day Limiting Condition for Operation time limit was exceeded.

Material Nonconformance Report 00669-83 was issued to initiate corrective action. The event had no affect on the health and safety of the public and did not constitute a threat to plant safety. This is a final report.

Yours truly,

L. F. Dale  
Manager of Nuclear Services

EBS/SHH:sap

cc: (See Next Page)

8309120502 830901  
PDR ADOCK 05000416  
S PDR

OFFICIAL COPY

IE 22  
1/0

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard  
Mr. R. B. McGehee  
Mr. T. B. Conner  
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555