



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

September 1, 1983

Mr. James G. Keppler, Director
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station Unit 2
10CFR50.55(e) Notification #83-05
Interim Report, G.E. HMA Relays
NRC Docket No. 50-374

Dear Mr. Keppler:

Commonwealth Edison notified your office on August 5, 1983 of a reportable deficiency in accordance with 10CFR50.55(e) concerning potentially defective HMA relays manufactured in 1974 by General Electric.

Safety related HMA relays with the date codes in question have been inspected for LSCS Unit 2. Within the group of approximately 135 relays 2 (two) were found to have insufficient armature clearance and have been adjusted. To assure that all desired relays have been inspected we are presently verifying the completeness of our HMA list.

Final resolution of the HMA relay problem is expected after September 23, 1983. At that time a final report will be issued.

If you or your staff have any questions concerning this activity please contact us at this office.

Very truly yours,

CW Schroeder 9/1/83

C. W. Schroeder
Nuclear Licensing Administrator

lm

cc: Director of Inspection & Enforcement
Washington, D.C.
NRC Resident Inspector - LSCS

8309130179 830901
PDR ADOCK 05000374
S PDR

7235N

IE27
SEP 7 1983 410