




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 2, 1983

W3I83-0293  
Q-3-A35.07.78



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 78  
"American Bridge Structural Steel Deficiencies"  
Third Interim Report

REFERENCE: LP&L Letter W3I83-0196 dated June 15, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC by August 31, 1983.

At the present time, the corrective action and the engineering and Quality Assurance review of the supporting documentation is expected to be completed by October 7, 1983.

A Final Report will therefore be submitted to the USNRC by October 28, 1983

Very truly yours,

F. J. Drummond  
Manager, Engineering & Technical Services

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8309230099 830902  
PDR ADDCK 05000382  
S PDR

IE-27

110