




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 2008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 2, 1983

W3I83-0296

Q-3-A35.07.32



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 32
"Stress Analysis for Welded Pipe Support Attachments Was Not
Performed Prior to Fabrication"
Fifth Interim Report

REFERENCE: LP&L Letter No. W3I83-0219, dated June 23, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 31, 1983.

At the present time, the supporting documentation is under review and is expected to be completed by October 14, 1983.

A Final Report will be submitted by October 28, 1983.

Very truly yours,

F. J. Drummond
Manager, Engineering & Technical Services

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8309230110 830902
PDR ADDCK 05000382
S PDR

IE-27 110