


**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 2, 1983

W3I83-0297  
Q-3-A35.07.84

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 84  
"Tube Track Welding Deficiencies"  
Second Interim Report

REFERENCE: LP&L Letter No. W3I83-0214, dated June 15, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of an update or Final Report to the USNRC no later than August 31, 1983.

At the present time, the date for corrective action completion for SCD No. 84 has been scheduled for November 15, 1983.

Therefore, a Final Report will be submitted by November 29, 1983 to the USNRC.

Very truly yours,

F. J. Drummond  
Manager, Engineering & Technical Services

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

- 3) Mr. E. L. Blake
- 4) Mr. W. M. Stevenson

8309230117 830902  
PDR ADDCK 05000382  
S PDR

IE-27

110