




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 2, 1983

W3I83-0294
Q-3-A35.07.56



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 56
"RCB Liner Plate Nuclear Coatings Failures"
Fifth Interim Report

REFERENCE: LP&L Letter W3I83-0223 dated June 29, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC by September 15, 1983.

At the present time, the completion of corrective action including the final inspection is scheduled for October 28, 1983.

A Final Report will therefore be submitted to the USNRC by November 18, 1983.

Very truly yours,

F. J. Drummond
Manager, Engineering & Technical Services

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8309230145 830902
PDR ADOCK 05000382
S PDR

10
IE-27