




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 9, 1983

W3I83-0305  
Q-3-A35.07.70

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 70  
"GE 480-V Trip Coils Do Not Drop Out After Tripping"  
Fourth Interim Report

REFERENCE: LP&L Letter W3I83-0227 dated June 22, 1983

Dear Mr. Collins:

The above referenced letter indicated that a Final Report would be submitted to the USNRC by September 12, 1983.

At the present time, all corrective action has been completed and the supporting documentation is currently under review. A Final Report will therefore be submitted to the USNRC by October 11, 1983.

Very truly yours,

F. J. Drummond  
Nuclear Services Manager

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

4) Mr. W. M. Stevenson