

Dmb



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

September 14, 1983


Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

On September 1, 1983, notification was made to Mr. E.R. Swanson at 1715 hours that we were removing Unit 2 from service to perform an inspection of the tie-down features of the Pressurizer Enclosure Ventilation System to confirm the statement made in our August 31, 1983, letter (Docket No. 50-315). This inspection confirmed that adequate tie-downs were installed and the Unit was immediately returned to service.

Sincerely,


W.G. Smith, Jr.

/bab

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

SEP 19 1983

8309230349 830914
PDR ADOCK 05000316
Q PDR

IE22
110