

THE TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION  
EMERGENCY PLAN SUPPORTING PROCEDURES  
REVISION INDEX

<u>Page</u>	<u>Revision</u>	<u>Procedures</u>	<u>Revision</u>	<u>Temporary Modification</u>
i	7	HP 1602.01	14	
		HP 1604.01	5	
		HP 1604.02	0	
		AD 1827.01	4	
		AD 1827.02	10	
		AD 1827.03	3	
		AD 1827.04	2	
		AD 1827.05	2	
		AD 1827.06	2	T-7248
		AD 1827.07	3	
		AD 1827.08	2	
		AD 1827.09	2	
		AD 1827.10	13	
		AD 1827.11	5	
		AD 1827.12	10	
		AD 1827.13	6	
		AD 1827.15	5	
		AD 1827.16	2	
		AD 1827.17	5	
		AD 1850.04	6	
		AD 1850.05	7	
		AD 1850.06	2	T-7399

Administrative Memorandums

		<u>Revision</u>
No. 37	ECS Pager and Telephone Numbers	30
No. 38	First Aid Team	12
No. 39	Fire Brigade	16
No. 41	Emergency Duty Officer (EDO)	28
No. 42	Radiation Monitoring Teams (RMT)	19

Revision 189  
September, 1983

DAVIS-BESSE NUCLEAR POWER STATION - UNIT 1  
TEMPORARY MODIFICATION REQUEST

ED 6926

DISTRIBUTION

☒ Original, Responsible Section Head Action  
☐ File Copy, Master File

COPIES TO BE MODIFIED FOR IMMEDIATE IMPLEMENTATION

Technical Support Center

SECTION 1

PROCEDURE TITLE AND NUMBER

Radiation, Containment & Airborne Radioactivity Monitoring During Emergencies at the

REASON FOR CHANGE Davis-Besse Administration Building (DBAB) AD 1850.06

NRC Commitment, as per Toledo Edison response dated June 21, 1983 (Serial No. 1-358).

CHANGE Page 3:  
Add Section: 3.4.5

The Radcon Operations Manager (located in the Technical Support Center) shall, during radiological emergencies, ensure that personnel assigned to the Control Room and Operations Support Center are issued self-reading dosimetry as well as TLD's.

IS PROCEDURE REVISION REQUIRED

Yes

☐

No

☒

If no, this modification is valid until

*Until needed for PPK  
are built.*

PREPARED BY

Ron Durdal

DATE

8/29/83

APPROVED BY

*M. Dennis*

DATE

8-29-83

APPROVED BY

*Gary Downing*

DATE

8/29/83

SUBMITTED BY (Section Head)

*D. W. Bruden*

DATE

8/30/83

RECOMMENDED BY (SRB Chairman)

*Sam Downing*

DATE

8/30/83

QA APPROVED BY (Manager of Quality Assurance)

*E. J. Craft / ejs*

DATE

8/31/83

APPROVED BY (Station Superintendent)

*D. W. Bruden*

DATE

8/31/83

DAVIS-BESSE REVISION COVER SHEET

September 2, 1983

DATE

TO: Div of RRC

FROM: EMERGENCY PLANNING & PREPAREDNESS SUPV.

SUBJECT: Davis-Besse EMERGENCY PLAN SUPPORTING PROCEDURES Manual Changes

This letter transmits additions and revisions to the Davis-Besse

EMERGENCY PLAN SUPPORTING PROCEDURES Manual. Control Copy 50 B.

Instructions for the material are as follows:

REMOVE AND RETURN

INSERT

Revision Index, Revision 188

Revision Index, Revision 189

T-7399 in front of AD 1850.06

Date Revision Entered \_\_\_\_\_

Addressee Signature \_\_\_\_\_

RETURN TO THE OFFICE MANAGER - STOP #3050

X005  
1/2

THE TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION  
EMERGENCY PLAN SUPPORTING PROCEDURES  
REVISION INDEX

<u>Page</u>	<u>Revision</u>	<u>Procedures</u>	<u>Revision</u>	<u>Temporary Modification</u>
1	7	HP 1602.01	14	
		HP 1604.01	5	
		HP 1604.02	0	
		AD 1827.01	4	
		AD 1827.02	10	
		AD 1827.03	3	
		AD 1827.04	2	
		AD 1827.05	2	
		AD 1827.06	2	T-7248
		AD 1827.07	3	
		AD 1827.08	2	
		AD 1827.09	2	
		AD 1827.10	13	
		AD 1827.11	5	
		AD 1827.12	10	
		AD 1827.13	6	
		AD 1827.15	5	
		AD 1827.16	2	
		AD 1827.17	5	
		AD 1850.04	6	
		AD 1850.05	7	
		AD 1850.06	2	T-7399

Administrative Memorandums

		<u>Revision</u>
No. 37	ECS Pager and Telephone Numbers	30
No. 38	First Aid Team	12
No. 39	Fire Brigade	16
No. 41	Emergency Duty Officer (EDO)	28
No. 42	Radiation Monitoring Teams (RMT)	19

Revision 189  
September, 1983

X005

~~8309100151 830930~~  
~~82 AD86K 88000346~~  
CF

## DISTRIBUTION



Original, Responsible Section Head Action



File Copy, Master File

T-7399

DAVIS-BESSE NUCLEAR POWER STATION - UNIT 1  
TEMPORARY MODIFICATION REQUEST

ED 6926

COPIES TO BE MODIFIED FOR IMMEDIATE IMPLEMENTATION

Technical Support Center

## SECTION 1

## PROCEDURE TITLE AND NUMBER

Radiation, Containment &amp; Airborne Radioactivity Monitoring During Emergencies at the

REASON FOR CHANGE Davis-Besse Administration Building (DBAB) AD 1850.06

NRC Commitment, as per Toledo Edison response dated June 21, 1983 (Serial No. 1-358).

CHANGE Page 3:

Add Section: 3.4.5

The Radcon Operations Manager (located in the Technical Support Center) shall, during radiological emergencies, ensure that personnel assigned to the Control Room and Operations Support Center are issued self-reading dosimetry as well as TLD's.

IS PROCEDURE REVISION REQUIRED

Yes ☐No ☒

If no, this modification is valid until

*until needed for PPK  
are built.*

PREPARED BY

Ron Durdal

DATE

8/29/83

APPROVED BY

*M. Devine*

DATE

8-29-83

APPROVED BY

*Gary Downing*

DATE

8/29/83

SUBMITTED BY (Section Head)

*D. W. Breden*

DATE

8/30/83

RECOMMENDED BY (SRB Chairman)

*Sm. Owens*

DATE

8/30/83

QA APPROVED BY (Manager of Quality Assurance)

*E. Kraft / egs*

DATE

8/31/83

APPROVED BY (Station Superintendent)

*T. M. Muen*

DATE

8/31/83

0.4/HP

DAVIS-BESSE REVISION COVER SHEET

September 2, 1983

DATE

TO:

Dir of NRC

FROM: EMERGENCY PLANNING & PREPAREDNESS SUPV.

SUBJECT: Davis-Besse EMERGENCY PLAN SUPPORTING PROCEDURES Manual Changes

This letter transmits additions and revisions to the Davis-Besse

EMERGENCY PLAN SUPPORTING PROCEDURES

Manual. Control Copy 50A.

Instructions for the material are as follows:

REMOVE AND RETURN

INSERT

Revision Index, Revision 188

Revision Index, Revision 189

T-7399 in front of AD 1850.06

Date Revision Entered \_\_\_\_\_

Addressee Signature \_\_\_\_\_

RETURN TO THE OFFICE MANAGER - STOP #3050

X005  
1/2