

THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201  
October 10, 1983  
LOZ-83-0171

J. WILLIAMS, JR.  
SENIOR VICE PRESIDENT  
NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler  
Regional Administrator

Gentlemen:

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1  
10CFR50.55(e), ITEM E-20, INADEQUATE CABLE  
TRAY HANGER INSPECTION  
W.O. 57300, JOB E-5590, FILE NO. 956C,

This letter constitutes an interim report concerning the subject condition initially reported to the Commission on May 3, 1982 as a potentially reportable deficiency under the requirements of 10CFR50.55(e).

Our previous interim report, LOZ-83-0055, dated June 20, 1983, reported that a reinspection program for accessible cable tray hanger and conduit support welds would be made available for NRC review prior to implementation.

On August 11, 1983, the proposed program, which includes sample visual inspections and destructive testing for determining allowable stresses, was presented to the NRC. Formal submittal of the program, including a request for relaxation of the NRC November 12, 1982 "Order to Show Cause and Order Immediately Suspending Construction" (CLI-82-33) per Section IV.B (3) will be made by November 8, 1983.

8310170448 831010  
PDR ADOCK 05000358  
S PDR

OCT 11 1983


282710

Mr. J.G. Keppler  
Regional Administrator  
October 10, 1983  
LOZ-83-0171  
Page 2

We trust the above will be found acceptable as an interim report under 10CFR50.55(e).

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By   
J. WILLIAMS, JR.  
SENIOR VICE PRESIDENT

RRW/sfr

cc: NRC Office of Inspection & Enforcement  
Washington, D.C. 20555  
NRC Resident Site Supervisor  
ATTN: W.M. Hill  
NRC Zimmer Project Inspector, Region III  
ATTN: E. R. Schweibinz