

Docket No. 50-346

License No. NPF-3

Serial No. 993

October 7, 1983



RICHARD P. CROUSE  
Vice President  
Nuclear  
(419) 259-5221

Director of Nuclear Reactor Regulation  
Attention: Mr. John F. Stolz  
Operating Reactor Branch No. 4  
Division of Operating Reactors  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Stolz:

This is in response to your letter dated September 6, 1983 (Log No. 1360), concerning the instrumentation to detect Inadequate Core Cooling (ICC). In your letter you requested Toledo Edison to provide a schedule to respond to the information requested in enclosure 2 of your letter.

There are a total of 12 items listed in the enclosure 2 of your letter. Toledo Edison will respond to items No. 2, 3, 6, 7, 8 and 11 by December 9, 1983 and the remaining items by February 10, 1984 for the Davis-Besse Nuclear Power Station Unit No. 1.

Very truly yours,

*R P Crouse*

RPC:FYC:jmh

cc: DB-1 NRC Resident Inspector

8310170599 831007  
PDR ADOCK 05000346  
P PDR

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

A002  
1/0