

Unit 2

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 4		6 9		FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	H	28	0	0	0	29	NA	30	B	31	Surveillance testing	
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA	35	NA	36				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION							
1	7	0	0	0	37	Z	38	NA	39				
PERSONNEL INJURIES		NUMBER		DESCRIPTION									
1	8	0	0	0	40	NA	41						
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
1	9	Z	42	NA	43								
PUBLICITY		ISSUED		DESCRIPTION									
2	0	N	44	NA	45								

8310170658 831007  
PDR ALOCK 05000328  
S PDR

IE22 NRC USE ONLY

8310170658 831007  
PDR ALOCK 05000328  
S PDR

TE 22

NRC USE ONLY \*

15

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

October 7, 1983

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE  
REPORT SCRO-50-328/83121

The enclosed report provides details concerning the failure of the lower  
containment airlock to meet overall leakage criteria. This report is  
submitted in accordance with Sequoyah unit 2 Technical Specification  
6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
J. A. Loper  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30330

C Inspector, Sequoyah

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

October 7, 1983

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE  
REPORT SORO-50-328/83121

The enclosed report provides details concerning the failure of the lower  
containment airlock to meet overall leakage criteria. This report is  
submitted in accordance with Sequoyah unit 2 Technical Specification  
6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
J. A. Long  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY

TC 2211