



Commonwealth Edison  
Quad Cities Nuclear Power Station  
22710 200 Avenue North  
Dordova, Illinois 61242  
Telephone 309/654-2241

DmB

NJK-83-367

Telecopy: Region III, Attention Mr. N. Chrissotimos

October 12, 1983

J. Keppler, Regional Administrator  
Office of Inspection and Enforcement  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station  
Docket Number 50-265, DPR-30, Unit Two  
Appendix A, Section 6.6.B.1.c

The purpose of this letter is to provide you with notification of a Reportable Occurrence as required by Technical Specification 6.6.B.1 within 24 hours of the occurrence.

At 1600 hours, on October 11, 1983, Lambert, McGill and Thomas, Incorporated Testing personnel were performing an ultrasonic inspection of the Unit 2 Cleanup System piping, as required by the ISI testing program, when a crack indication was identified in the heat affected zone of weld 125-S27 of line 2-1202-6" A. This weld is an elbow to pipe weld located outside the Primary Containment between penetration X-14 and the outboard containment Isolation valve, MD 2-1201-5. Unit 2 is currently in the COLD SHUTDOWN condition for refueling.

This occurrence was discussed by telephone with Mr. Chrissotimos of your office on October 12, 1983. Further information will be provided by Reportable Occurrence Report RO 50-83/18-01T, which will be submitted within 14 days of the date of this occurrence.

Respectfully,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

*L. J. Gervier for*  
N. J. Kalivianakis  
Station Superintendent

NJK:DGC/bb

cc B. Rybak

8310170661 831012  
PDR ADJCK 05000265  
S PDR

IE22

10-12-83  
11:50  
JC