



300 Madison Avenue  
Toledo, OH 43652-0001  
419-249-2300

John P. Stetz  
Vice President - Nuclear  
Davis-Besse

Docket Number 50-346

License Number NPF-3

Serial Number 2270

February 8, 1995

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Subject: Summary Report for Ninth Refueling Outage Inservice  
Inspection Activities  
Davis-Besse Nuclear Power Station - Unit 1

Gentlemen:

In accordance with the 1986 Edition of the American Society of  
Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section XI,  
IWA-6000, enclosed is the subject report covering inservice inspection  
activities, and repairs and replacements completed through the end of  
the Davis-Besse Nuclear Power Station, Unit 1 ninth refueling outage.

Should you have any questions regarding the enclosed report, please  
contact Mr. William T. O'Connor, Manager - Regulatory Affairs, at  
(419) 249-2366.

Very truly yours,

A handwritten signature in dark ink, appearing to read 'John P. Stetz'.

NKP/eld

Enclosure

cc: L. L. Gundrum, NRC Project Manager  
J. B. Martin, Regional Administrator, NRC Region III  
S. Stasek, DB-1 NRC Senior Resident Inspector  
Factory Mutual Engineering Associates (2)  
Ohio Department of Industrial Relations  
Utility Radiological Safety Board

100040

Operating Companies:  
Cleveland Electric Illuminating  
Toledo Edison

9502160398 950208  
PDR ADDCK 05000346  
Q PDR

AD47

# **NINTH REFUELING OUTAGE INSPECTION INSPECTION SUMMARY REPORT**

**DAVIS-BESSE NUCLEAR POWER STATION  
UNIT 1**



**DAVIS-BESSE NUCLEAR POWER STATION**