

## LICENSEE EVENT REPORT

CAR 1424

CONTROL BLOCK: 

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	R	E	G	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																																																			
7	8	9										14										15										25										26										30										57										58									
		LICENSEE CODE																				LICENSE NUMBER																				LICENSE TYPE																																							

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 2 4 4 7 0 1 0 5 8 3 8 0 2 0 4 8 3 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During the performance of ISI-7, High Energy Piping Leakage Inspection a QC

0 3 | Inspector identified Main Steam Snubber #160 was inoperable due to the piston rod

0 4 | becoming detached from the piston. This is an LCO based on Tech. Spec. 3.13.2

0 5 |

0 6 |

0 7 |

0 8 |

SYSTEM CODE 0 9		CAUSE CODE H B (11)		CAUSE SUBCODE E (12)		COMPONENT CODE S U P P O R T (14)		COMP. SUBCODE D (15)		VALVE SUBCODE Z (16)	
7 8		9 10		11 12		13 18		19 20		21 22	
(17) LER/RO REPORT NUMBER		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 0 2		OCCURRENCE CODE / 3		REPORT TYPE /		REVISION NO. /	
23 24		25 26		27 28		29 30		31 32		33 34	
ACTION TAKEN C (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 (22)		ATTACHMENT SUBMITTED N (23)	
35 36		37 40		41 42		43 44		45 46		47 48	
NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER B 2 0 9 (26)							
49 50		51 54		55 56		57 58		59 60		61 62	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The snubber in position MS160 was removed and replaced by a spare snubber. The

1 1 | failed snubber was tested and verified to be operable, was repaired by re-attaching

1 2 | the piston rod to the piston and was returned to stock.

1 3 |

1 4 |

7 8 9 FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 5 E 10 0 0 NA B Performance of Procedure ISI-7

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	(37) Z	(38) NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
1	0	0	0	40	NA

LOSS OF OR DAMAGE TO FACILITY					
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	

8302230586 830204  
BBB ABCK 05000244

PUBICITY		ISSUED		DESCRIPTION		PDR ADUCK 09000244 S PDR		NRC USE ONLY													
2	0	N	(44)	NA																	
7	8	9	10							68	69										

NAME OF PREPARER James C. Bodine

PHONE: 315-524-4446 Ext. 241