

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 1 2 0 8 3 8 0 2 0 3 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While the plant was shutdown, "A" laundry drain tank was placed in a recirc. line-up
0 3 with the discharge line-up still available. This resulted in an un-planned release
0 4 of 130 gallons of laundry effluent prior to sample. Environmental Tech. Spec. 2.3.
0 5 A.2 requires a sample prior to batch release. Because the effluent monitor was oper-
0 6 able during this release, the release was properly monitored. This event posed no
0 7 threat to public health or safety.

0 8 7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16
M A 11 A 12 B 13 Z Z Z Z Z Z Z 14 Z 15 Z 16
17 LER RO REPORT NUMBER 18 8 3 19 20 21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
G 18 H 19 Z 20 Z 21 0 0 0 0 0 22 N 23 N 24 Z 25 7 9 9 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 When the operator noticed a decrease in "A" laundry tank level, the pump was se-
1 1 cured and the discharge valve was shut. This valve is common to both tanks. The
1 2 operator involved was counselled on adhering to procedures. Procedure F-OP-49 will
1 3 be revised to caution operators. In addition, a modification has been submitted to
1 4 split the line-up of these two tanks.

1 5 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
G 28 0 0 0 29 NA A 31 Operator Observation

1 6 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
L 33 M 34 20.3 Microcuries Total Laundry Drain Tank to Discharge Canal

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
0 37 Z 38 NA

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
0 40 NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
Z 42 NA

2 0 PUBLICITY ISSUED DESCRIPTION 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
N 44 NA

NAME OF PREPAREP Roger Locy

PHONE (315) 342-3840

8302230594 830203
PDR ADOCK 05000333
S PDR

NRC USE ONLY