

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

February 17, 1983

RECEIVED
NRC

1983 FEB 22 PM 1:04

SCE

REGION V

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-002
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H.B. Ray (SCE) to R.H. Engelken (NRC) dated
December 15, 1982

Pursuant to Section 6.9.1.13.c of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre, Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Technical Specification Section 4.0.2 regarding Surveillance Requirement 4.4.5.2.1.c associated with Limiting Condition for Operation (LCO) 3.4.5.2. Enclosed LER 83-002 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,

HB Ray / NRC

Enclosure: LER 83-002

8303040567 830217
PDR ADOCK 05000362
S PDR

IE-20
83-74

February 17, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)