



Northern States Power Company

Monticello Nuclear Generating Plant
2807 West Hwy 75
Monticello, Minnesota 55362-9637

January 20, 1995

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Inservice Inspection (ISI) Examination
Summary Report - Refueling Outage No. 17

Enclosed for your information are four copies of the Inservice Inspection (ISI) examination summary report for the 1994 Monticello refueling outage (Refueling Outage No. 17). The 1994 outage represented the second inspection conducted for first period of Monticello's third 10-year ISI interval.

The enclosed report identifies components examined, the examination methods used, the examination number, and summarizes the results. The examination plan focused on: 1) the pressure retaining components and their supports associated with the reactor coolant system and associated systems classified as ASME Classes 1 and 2, 2) reactor vessel examination, 3) system pressure testing, and 4) snubber inservice testing. All anomalies were either corrected or an engineering evaluation was performed to accept "as-is" conditions.

This letter contains no new NRC commitments, nor does it modify any prior commitments.

Please contact Marv Engen, Sr Licensing Engineer, at (612) 295-1291 if you require additional information.

William J Hill
Manager
Monticello Nuclear Generating Plant

c: See next page

1/18/95 WSP H:\DATA\NRCCORR\RFO17\ISI

9501300133 950120
PDR ADOCK 05000263
P PDR

USNRC

January 20, 1995

Page 2

NORTHERN STATES POWER COMPANY

- c: Regional Administrator-III, NRC (2 copies of attachment)
 NRR Project Manager, NRC (w/o attachment)
 Resident Inspector, NRC (1 copy of attachment)
 J Silberg (w/o attachment)
 B Kubitshek, Chief Boiler Inspector, State of MN (1 copy of attachment)
 Paul Fisher, Hartford Ins. (1 copy of attachment)

Enclosure

TRANSMITTAL MANIFEST

NORTHERN STATES POWER COMPANY

NUCLEAR LICENSING DEPARTMENT

MONTICELLO NUCLEAR GENERATING PLANT

Inservice Inspection (ISI) Examination
Summary Report - Refueling Outage No. 17

Correspondence Date: January 20, 1995

Monticello Internal Site Distribution Special Instructions

Kaleen Hilsenhoff USAR File Yes__ No_x_
Steve Ludders NRC Commitment Yes__ No_x_
Lila Imholt Monti OC Sec Yes__ No_x_ - 10, No dist to OC members below if YES
Mel Opstad Monti SAC Sec Yes__ No_x_ - 6
*Mail Room Monti Posting Yes__ No_x_ - 7

Monticello Internal Site Distribution:

**Monti Document Control File	J C Grubb, NGSS, OC
W J Hill, Plant MGR, SAC, OC	L L Nolan, GSSA, OC
C A Schibonski, GSE, OC	B D Day, MGR MTC, OC
M F Hammer, GSM, OC	Operating Experience Coord
J E Windschill, GSRS, OC	W A Shamla, NQD
M W Onnen, GSO, OC	**Monti Site Lic File
Alan Wojchowski	**Steve Ray, SR Res Insp, NRC
** Dean Carstens	

NSP Internal Distribution

E L Watzl	R O Anderson, Dir LMI, SAC
**J L Ricker	Communications Dept Yes_x_ No__
**M M Vik	

External NSP Distribution

**Doc Control Desk, NRC - 4 copies of Encl	Kris Sanda, State of Minn
**Regional Admin-III, NRC - 2 copies of Encl	J E Silberg,
Beth Wetzel, NRR-PM, NRC	**Minn State Boiler Inspector
	**Paul Fisher (Hartford Ins)

**Includes copies of the summary report, advance Distribution made by Site Licensing.

Manifest Date: January 20, 1995