



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 3, 1984

W3K84-0246
Q-3-A35.07.32

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K83-1665 dated October 28, 1984

Dear Mr. Collins:


SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 32
"Stress Analysis For Welded Pipe Supports Was Not Performed Prior
To Fabrication"
Seventh Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on February 3, 1984.

At the present time, the supporting documentation review is continuing and is scheduled to be completed in late February 1984.

The Final Report will be submitted to the USNRC on March 9, 1984.

Very truly yours,



T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8402140060 840203
PDR ADOCK 05000382
S PDR

IE-27
1/0

Mr. John T. Collins
February 3, 1984
W3K84-0246
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130