



January 23, 1984
L-84-17

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 and 4
St. Lucie Units 1 & 2
Docket Nos. 50-250, 50-251, 50-335, 50-389
IE Bulletin 83-06

Our letter, L-83-577, dated December 6, 1983, provided our initial response to IE Bulletin 83-06 (Nonconforming materials supplied by Tube-Line Corporation Facilities at Long Island City, New York; Houston, Texas; and Carol Stream, Illinois).

The purpose of this letter is to supply information which was not available at the time of our initial response. We have now received a response from the B.F. Shaw Company of Wilmington, Delaware and have found that no additional Tube-Line materials beyond those identified in our initial response were supplied to FPL.

We have also been notified that no additional Tube-Line materials from the period of concern were obtained by our architect engineers or their sub-tier suppliers for Turkey Point Units 3 & 4 or St. Lucie Units 1 & 2.

The two four-inch elbows in the shield building ventilation system which were discussed in our initial response will be replaced.

This completes our response to the action items of the Bulletin. Should you or your staff have any questions on this information, please contact us.

Very truly yours,

J. W. Williams, Jr.
J. W. Williams, Jr.
Vice President
Nuclear Energy Department

JWW/PLP/js

Attachment

8402140076 840123
PDR ADOCK 05000250
G PDR

cc: Mr. James P. O'Reilly, Region II
Harold F. Reis, Esquire
PNS-LI-84-29