

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

January 30, 1984

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 2
Docket No. 50-370
LER/RO-370/83-92

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-370/83-92 was to have been submitted by January 30, 1984. This 30 day Reportable Occurrence (pursuant to T.S. 6.9.1.11) concerns an event with the Reactor Coolant System (cold shutdown - loops not filled, T.S. 3.4.1.4.2) which occurred on December 31, 1983. At this time investigation of the incident and preparation of a report are not yet complete. The report will be submitted by February 8, 1984.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8402140185 840130
PDR ADDCK 05000370
S PDR

OFFICIAL COPY

JF22

110