




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

January 31, 1984

W3K84-0208
Q-3-A35.07.78



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-2029 dated December 23, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 78
"American Bridge Structural Steel Deficiencies"
Sixth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC January 31, 1984.

At the present time, additional work is required to complete two (2) Nonconformance Reports (NCR's). This work and supporting documentation verification is scheduled to be completed by the end of February 1984.

A Final Report will be submitted to the USNRC on March 9, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8402140395 840131
PDR ADOCK 05000382
S PDR

IE-27/10

Mr. John T. Collins
January 31, 1934
W3K84-0208
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130