




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

January 31, 1984

W3K84-0209
Q-3-A35.07.42R1



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-1957 dated December 13, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 42-R1
"HMA Auxiliary Relays"
Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on January 31, 1984.

At the present time, a plant electrical outage is scheduled to complete the final corrective action in early February 1984.

The Final Report will be submitted to the USNRC on February 24, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8402140431 840131
PDR ADDCK 05000382
S PDR

IE-27
1/0

Mr. John T. Collins
January 31, 1984
W3K84-0209
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Moaroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130