

# PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6567

JAMES D. SHIFFER  
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS  
NUCLEAR POWER GENERATION

February 6, 1984

PG&E Letter No.: DCL-84-042

Mr. John B. Martin, Regional Administrator  
U. S. Nuclear Regulatory Commission, Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, CA 94596-5368

Re: Docket No. 50-275, OL-DPR-76  
Diablo Canyon Unit 1  
Special Report on Non-Functional Fire Barriers, SR 84-01

Dear Mr. Martin:

Pursuant to Section 6.9.2 of Appendix A of the Diablo Canyon Unit 1 Operating License, and as specifically required by Technical Specification 3.7.10, this Special Report is submitted concerning fire barriers in safety related areas being non-functional for greater than seven (7) days.

On December 30, 1983, installation of a conduit through a fire barrier wall in the cable spreading room rendered the fire barrier non-functional. The work was completed and the fire barrier declared functional on January 7, 1984.

Four (4) fire doors were removed on January 7, 1984, and replaced with heavy duty pressure fire doors. The replacement was completed on January 26, 1984.

On January 9, 1984, during the removal and modification of the main steam line whip restraints, six (6) fire barrier penetrations were made non-functional. The fire barrier penetrations will be restored prior to heat-up of the Reactor Coolant System.

Additionally, on January 16, 1984, construction crews removed a fire door and frame to repair a mount bolt. The frame has been replaced and sealed with fire retardant caulking.

REGIONAL

1984 FEB -7 AM 10:39

8402150356 840206  
PDR ADOCK 05000275  
S PDR

RECEIVED  
INFO


1/6 IE-22

Mr. J. B. Martin  
PGandE Letter No.: DCL-84-042  
February 6, 1984  
Page Two

In accordance with Technical Specification 3.7.10a, fire watches or patrols were established for each case within one hour. Specification 3.7.10a requires submittal of this Special Report as the fire barriers remained non-functional for greater than seven (7) days.

These conditions have in no way affected the public's health and safety.

Sincerely,

A handwritten signature in cursive script, appearing to read "J. W. Knighton".

cc: G. W. Knighton

Director, Office of Management Information  
and Program Control

Service List