

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

February 1, 1984
ANPP-28773-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-77
A 50.55(e) Potentially Reportable Deficiency Relating To Unit
2 Concrete Pour (2-C123) Contains Honey Combed Concrete Around
the Vertical Tendon Sheath Block-Outs.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and K. Parrish on
November 9, 1983.
(B) ANPP-28359, dated December 6, 1983 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
February 9, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by May 18, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:db

cc: See Page Two

8402150374 840201
PDR ADDCK 05000529
S PDR

IE-27 110

Mr. T. W. Bishop
DER 83-77
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339