

# LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 100-000000-000341111145  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 REPORT SOURCE L6050003115708298380928839  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING REFUELING OUTAGE, MODE 6, THE FIRE DOOR LEADING TO THE CONTRACTOR ACCESS  
03 AREA WAS INADVERTANTLY DAMAGED WHEN THE DOOR WAS CLOSED WITH A PIECE OF STEEL  
04 BETWEEN THE DOOR JAM AND THE EDGE OF THE DOOR. THE TWO BOTTOM HINGES BROKE. THE  
05 DOOR HAD BEEN PROPPED OPEN FOR VENTILATION PURPOSES AND WAS UNDER CONTINUOUS FIRE  
06 WATCH BY A SECURITY OFFICER. THE FIRE WATCH WAS CONTINUED UNTIL THE DOOR WAS  
07 REPAIRED. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

08

09 SYSTEM CODE AB 11 CAUSE CODE A 12 CAUSE SUBCODE E 13 COMPONENT CODE XXXXX 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER 83 21 22 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB N 24 PRIME COMP SUPPLIER Z 25 COMPONENT MANUFACTURER X999 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE INDIVIDUALS INVOLVED DID NOT NOTICE THE DOOR BLOCK. THEY WERE ADMONISHED TO  
11 USE GREATER CAUTION. THE DOOR WAS IMMEDIATELY REPAIRED AND RETURNED TO OPERABLE  
12 STATUS.

13

14

15 FACILITY STATUS H 28 % POWER 010 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION SECURITY OFFICER OBSERVATION 32  
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE  
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N/A 39  
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N/A 41  
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
7 8 9 10 80

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45  
7 8 9 10 80

NAME OF PREPARER D.K. Welcher

PHONE (616) 465-5901

NRC USE ONLY

IE 22



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

September 28, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report is submitted:

RO 83-091/03L-0

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/clm

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee  
INFO  
PISRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

SEP 30 1983

IE2211