

CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina 29550

Company Correspondence

JAN 31 1984

Robinson File No: 13510E

Serial RSEP/84-72

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
NRC IE INSPECTION REPORT IER-83-26


Dear Mr. O'Reilly:

Carolina Power and Light Company's (CP&L) December 1, 1983 response to violation "B" of the subject report, stated that a supplemental response would be provided by January 31, 1984. The violation concerned not plugging two steam generator tubes in which a later review of the eddy current tapes indicated that the two tubes should have been plugged. Corrective action was to shut down the Plant and to inspect and plug the appropriate tubes.

The supplemental response was to discuss additional corrective actions to prevent recurrence of the root cause of the problem which involved the review process of the eddy current tapes. The supplemental response is not completed at this time. The supplemental response will be provided by February 29, 1984.

If you have any questions concerning this information, please contact my staff or me.

Very truly yours,



R. E. Morgan
General Manager
H. B. Robinson S. E. Plant

CLW/tld

8402280170 840209
PDR ADOCK 05000261
Q PDR