

GULF STATES UTILITIES COMPANY


POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631



February 16, 1984
RBG-17,007
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-89

Gulf States Utilities Company has not completed its investigation of DR- 89 concerning the RTE primary knife-type disconnect used on the Standby Diesel Generator. An interim or final status report will be provided by March 20, 1984.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8402280371 840216
PDR ADOCK 05000458
S PDR

IE-27.10