

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	57 CAT 58		

CON'T

0	1
---	---

REPORT SOURCE

L	(6)	0	5	0	0	0	3	1	6	(7)	1	0	0	3	8	3	(8)	1	1	0	2	8	3	(9)
---	-----	---	---	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

9 2 DURING SHIFT SURVEILLANCE OF THE RMS THE OPERATOR RECORDED THE WRONG DATA FOR

[03] CONTAINMENT PARTICULATE ACTIVITY. THE NEXT SHIFT DISCOVERED THE MISTAKE AND

0 4 | VERIFIED THE REQUIREMENTS OF THE ACTION STATEMENT WERE MET. THIS WAS

0 5 | NON-CONSERVATIVE WITH RESPECT TO T.S. 3.3.3.1 THE HEALTH AND SAFETY OF THE

06 PUBLIC WERE NOT AFFECTED. SIMILAR INCIDENT WAS REPORTED VIA LER 50-316/83-064.

0	9	M	C	A	B	I	N	S	T	R	U	P	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	

(17) LER/RO REPORT NUMBER [8 | 3] [—] SEQUENTIAL REPORT NO. [0 | 9 | 8] [/] OCCURRENCE CODE [0 | 3] REPORT TYPE [L] [—] REVISION NO. [0]

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
X	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	L	25	E	0	7	0	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE RADIATION MONITORING SYSTEM DATA IS DISPLAYED ON AN EBERLINE CRT. THE

11 | OPERATOR THOUGHT THE READINGS IN COLUMN ONE WERE FOR THE FIRST CHANNEL. TO AVOID

1 2 FURTHER CONFUSION, THE CRT DISPLAY WAS EDITED TO REDUCE OPERATION CONFUSION.

1	3	NO FURTHER ACTION IS PLANNED.
---	---	-------------------------------

14

1 5 FACILITY STATUS (28) % POWER 1 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	Z	(33)	Z	(34)	NA			NA		

PERSONNEL EXPOSURES						44	45	80
		NUMBER	TYPE	DESCRIPTION	(39)			
1	2	a	a	d(37)	z	(38)	NA	

		PERSONNEL INJURIES			DESCRIPTION		(41)		
		NUMBER							
1	8	9	11	12	13				80
						N7			

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60						
LOSS OF OR DAMAGE TO FACILITY (43)																																																											
TYPE DESCRIPTION																																																											

1	9	2	(42)	NA
---	---	---	------	----

PUBLICITY
ISSUED — DESCRIPTION (45) NRC USE ONLY

2	0	N	44	NA	
---	---	---	----	----	--

NAME OF PREPARER D. F. KRAUSE

PHONE (616) 465-5901

8311070307 831102
PDR ADCK 05000316
S PDR

0000976



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

Dmb

November 2, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following reports are submitted:

RO 83-098/03L-0

Sincerely,

E. L. Townley

Fol W.G. Smith, Jr.
Plant Manager

/ckm

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

NOV 4 1983

IE 22
4