




# Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

October 28, 1983  
Fort St. Vrain  
Unit No. 1  
P-83351



Mr. John T. Collins, Regional Administrator  
Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76011

Reference: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/83-036, Reportable Occurrence Report No. 50-267/83-037, Reportable Occurrence Report No. 50-267/83-039, and Reportable Occurrence Report No. 50-267/83-040, Finals, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/83-036, Reportable Occurrence Report No. 50-267/83-37, Reportable Occurrence Report No. 50-267/83-039, and Reportable Occurrence Report No. 50-267/83-040.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Manager, Nuclear Production

DW/djm

Enclosure

cc: Director, MIPC

H005  
|||

8311180236 831028  
PDR ADOCK 05000267  
S PDR