

EXHIBIT A

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
1 G 18	1 Z 19	1 Z 20	1 Z 21	1 0 1 0 1 0 1 0 22	1 Y 23	1 N 24	1 Z 25	1 Z 1 9 1 9 1 9 26
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

FACILITY

ACTIVITY

PERSONNEL EXPOSURES

PERSONNEL INJURIES

LOSS OF OR DAMAGE TO FACILITY

PUBLICITY

NAME OF PREPARER: Phillip B. Wade

PHONE: (501) 964-3100

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-368/83-047/03L-0

Occurrence Date: 10/23/83

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

Additionally, other procedures affecting core alterations were reviewed and verified to contain the requirement that the surveillance be performed prior to core alterations.




ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 22, 1983

2CAN118308

Mr. J. E. Gagliardo, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-047/03L-0

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification
5.9.1.9.b, attached is the subject report concerning a missed surveillance.

Very truly yours,

John R. Marshall
John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

14-22
11