



**PERRY NUCLEAR POWER PLANT**

10 CENTER ROAD  
PERRY, OHIO 44081  
(216) 259-3737

Mail Address:  
P.O. BOX 97  
PERRY, OHIO 44081

**Donald C. Shelton**  
SENIOR VICE PRESIDENT  
NUCLEAR

April 20, 1995  
PY-CEI/NRR-1941L

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Perry Nuclear Power Plant  
Docket No. 50-440  
LER 94-012-00 Status

Gentlemen:

LER 94-012-00, regarding equipment malfunctions which led to two unexpected automatic starts of the Annulus Exhaust Gas Treatment System (AEGTS), was submitted on June 13, 1994. A supplemental report identifying the root cause of the failure of a Fluid Controls Incorporated (FCI, Model Number FR 72-4) flow switch was planned to be submitted by October 15, 1994. Onsite evaluation of this switch failed to identify the root cause of the failure; therefore, the switch was sent to FCI on March 23, 1995 for additional failure analysis. The supplement to LER 94-012 will be submitted following an evaluation by Perry Nuclear Power Plant engineering personnel of the results of the failure analysis being performed by FCI.

If you have questions or require additional information, please contact Mr. James D. Kloosterman, Manager - Regulatory Affairs at (216) 280-5833.

Very truly yours,

Donald C. Shelton

GSC:sc

cc: NRC Project Manager  
NRC Resident Inspector  
NRC Region III

250051

Operating Companies  
Cleveland Electric Illuminating  
Toledo Edison

9504250205 950420  
PDR ADDCK 05000440  
S PDR

IF22  
1/0