

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALJMF2 000-000000-000 341111 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CONT

01 REPORT SOURCE L 05000364 7 102983 8 112883 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 2125 on 10/29/83, with the B train post accident hydrogen analyzer removed from
03 service for performance of FNP-2-STP-220.9 (Post Accident Hydrogen Analyzer 2A,
04 2B Calibration and Functional Test Q2E23AIT-2703 A & B), the A train analyzer
05 mode selector switch was inadvertently operated causing the A train analyzer to
06 become inoperable. Tech. Spec. 3.6.4.1 requires two independent containment
07 hydrogen analyzers to be operable. Tech. Spec. 3.0.3 action statement require-
08 ments were met. Health/safety of the public was not affected.

09 SYSTEM CODE SE 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE INSTRU 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
17 LER/NO REPORT NUMBER 83 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
18 ACTION TAKEN H 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0000 23 ATTACHMENT SUBMITTED N 24 NPRD-4 FORM SUB N 25 PRIME COMP. SUPPLIER A 26 COMPONENT MANUFACTURER DO96
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by personnel error. I&C personnel operated the A train
11 analyzer mode selector switch instead of the B train switch. The A train post
12 accident hydrogen analyzer was returned to service at 2135 on 10/29/83. The
13 personnel involved have been counseled. This incident has been discussed with
14 other I&C personnel who perform similar duties.

15 FACILITY STATUS E 28 % POWER 048 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 PERSONNEL EXPOSURES NUMBER 000 37 Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

20 PUBLICITY ISSUED DESCRIPTION N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156