

THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201

August 8, 1983

LOZ-83-0102

J. WILLIAMS, JR.
SENIOR VICE PRESIDENT
NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler
Regional Administrator

Gentlemen:

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1
10CFR50.55(e), ITEM Q-3, LACK OF INSPECTION
PERSONNEL QUALIFICATIONS
W.O. 57300, JOB E-5590, FILE NO. 956C, Q-3

This letter constitutes an interim report concerning the subject condition initially reported to the Commission on December 8, 1982 as a potentially reportable deficiency under the requirements of 10CFR50.55(e).

As identified in our last report, LOZ-83-0026, dated May 26, 1983, HJK is continuing the review of the 60,000 work packages to identify any inspection personnel whose qualifications or certifications were not properly documented.

At present, approximately 50% of the work packages have been reviewed and approximately 45% of the concerns identified from the packages reviewed have been satisfactorily resolved. No specific potentially reportable hardware concerns have been identified.

As part of the corrective actions, HJK has developed a program that will institute a comprehensive reevaluation of all HJK inspector certifications to evaluate compliance with Regulatory Guide 1.58, Revision 1. Those inspectors whose files do not reflect properly documented certification will have their training and qualifications reverified to establish whether they can be certified to the requirements of Regulatory Guide 1.58, Revision 1. Those inspectors whose qualifications are reverified and found to be acceptable shall be certified, including a statement that they possessed the qualifications to be certified at the time the inspections were performed. For those inspectors who are deemed non-certifiable,

8312120189 830808
PDR ADDCK 05000358
S PDR

AUG 10 1983

10 T827


Mr. J.G. Keppler
Regional Administrator
August 8, 1983
LOZ-83-0102
Page 2

Exception/Correction Notices (ECN's) shall be written to document and track the inspections previously performed by them. A complete list of all inspections performed by these inspectors will be compiled. From this list a sample reinspection plan will be developed and implemented. The sample plan will be in accordance with the Double Normal Sample Plan per MIL-STD-105D. Those items selected to be reinspected will be reinspected by certified inspectors to approved HJK Construction Inspection Plans.

A follow-up report will be submitted by November 19, 1983. We trust the above will be found acceptable as an interim report under 10CFR50.55(e).

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By 
J. WILLIAMS, JR.
SENIOR VICE PRESIDENT

DJS/BLT/sfr

cc: NRC Office of Inspection & Enforcement
Washington, D.C. 20555
NRC Senior Resident Inspector
ATTN: W.F. Christianson
NRC Zimmer Project Inspector, Region III
ATTN: E. R. Schweibinz