



**Florida  
Power**  
CORPORATION

December 5, 1983  
3F1283-06

Mr. James P. O'Reilly  
Regional Administrator, Region II  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, GA 30303

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
Licensee Event Report No. 83-050

Dear Mr. O'Reilly:

On November 4, 1983, a Florida Power Corporation Quality Program audit revealed that on July 19, 1983, a mode ascension occurred (Mode 5 to Mode 4) prior to completing a required surveillance. This is contrary to the requirements of T.S. 3.0.4.

Analysis of this occurrence is continuing and this Licensee Event Report will be submitted by December 22, 1983.

Should there be any questions, please contact this office.

Sincerely,

G.R. Westafer  
Manager  
Nuclear Operations Licensing and Fuel Management

AEF:jcf

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8312130091 831205  
PDR ADDCK 05000302  
S PDR

OFFICIAL COPY

IF22  
1/0