



LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

November 29, 1983


W3K83-1845
Q-3-A35.07.37

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L letter W3I83-0283 dated August 12, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 37
"Temperature Detectors (RTD) Failures"
Eighth Interim Report



The above referenced letter indicated submittal of a Final Report to the USNRC by December 6, 1983.

At the present time material has been received, corrective action and review of supporting documentation is scheduled to be completed by the end of December 1983.

A Final Report will be submitted to the USNRC on January 20, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets
Quality Assurance Manager

TFG:CNH:JC

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8312150004 831129
PDR ADCK 05000382
S PDR

IE-27
1/0

Mr. John T. Collins
November 29, 1983
W3K83- 1845
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130