



Carolina Power & Light Company

P. O. Box 165, New Hill, North Carolina 27562  
December 6, 1983

FILE: SH N-2/18  
Item 156

MQAH 83-374

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1  
DOCKET NO. 50-400  
FUEL POOL HEAT EXCHANGER OUTLET - MINIMUM WALL

Dear Mr. O'Reilly:


This is to confirm the December 2, 1983 telephone conversation between Mr. N. J. Chiangi (CP&L) and Mr. A. Hardin (NRC). Mr. A. Hardin was informed that the November 21, 1983 potentially reportable item, pertaining to violation of minimum wall thickness during field welding on the shell outlet of a fuel pool heat exchanger, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e).

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung  
Mr. G. Maxwell  
Mr. R. L. Prevatte

  
N. J. Chiangi - Manager  
Quality Assurance/Quality Control  
Harris Plant

8312160043 831206  
PDR ADOCK 05000400  
S PDR

OFFICIAL COPY

7527

110