



Carolina Power & Light Company

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

December 9, 1983

FILE: B09-13510C

SERIAL: BSEP/83-3846

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

Dear Mr. O'Reilly:

Further evaluation of the event reported in LER 1-83-28 (Serial: BSEP/83-2556), submitted to your office on August 8, 1983, has determined that the 1A core spray pump automatic load sequence relay, E21-K16A, was not inoperable as it actuated within the specified 10 percent of the required value. Therefore, the event is not reportable. Please void LER 1-83-28.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/joh/LETJH1

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8312160133 831209
PDR ADCK 03000325
S PDR

OFFICIAL COPY

LE22

1/0