



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

Dmb

December 6, 1983

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Generating Station Units 1 and 2
Reactor Coolant Pump Bearing Failure
NRC Docket Nos 50-454 and 50-455

References (a): June 9, 1983 letter from E. D. Swartz
to J. G. Keppler.

(b): September 23, 1983 letter from T. R. Tramm
to J. G. Keppler

Dear Mr. Keppler:

This letter provides a third interim report on the failure of a bearing on reactor coolant pumps 1A at Byron Generating Station. For NRC tracking purposes this deficiency is numbered 83-07.

In reference (b) we indicated that our final report of this bearing failure was to be issued in October, 1983. This is to inform you that the report is now expected to be available by January 15, 1984.

Please address questions regarding this matter to this office.

Very truly yours,

8312190027 831209
PDR ADOCK 05000454
S PDR

T. R. Tramm
Nuclear Licensing Administrator

lm

cc: Director of Inspection and Enforcement
NRC Resident Inspector - Byron

7712N

IE27
DEC 8 1983 1/0