



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

DMP

December 6, 1983

Mr. James G. Keppler, Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Generating Station Unit 1
Preservice Inspection Weld Indications
NRC Docket No. 50-454

Reference (a): May 26, 1983 letter from E. D. Swartz
to J. G. Keppler

(b): October 27, 1983 letter from T. R. Tramm
to H. R. Denton

Dear Mr. Keppler:

This is to provide a final report on several rejectable weld indications in the pressurizer and two steam generators at Byron 1. For NRC tracking purposes this deficiency was assigned number 83-05.

In reference (a) Commonwealth Edison reported that several weld indications had been found during the preservice inspection program and we indicated that additional NDE testing would be performed. Reference (b) documented the results of all of the examinations and our plans repair of indications in the steam generators. We also provided our basis for not pursuing repair of the pressurizer indications and requested NRC concurrence.

Since reference (b) provides complete details of these indications and our planned corrective actions, that report should suffice as a final report on the 50.55 (e) reportable deficiency.

Please direct further questions to this office

Very truly yours,

T. R. Tramm
Nuclear Licensing Administrator

bg/lm

cc: Director of Inspection and Enforcement
NRC Resident Inspector - Byron

7713N

8312190162 831206
PDR ADOCK 05000454
S PDR

DEC 8 1983

IE 27

1/0