

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: 305/245-2910 X-200

8312200051 831212
PDR ADCK 05000250
S PDR

Additional Corrective Actions

Operations and Chemistry personnel have acknowledged the need for closer coordination when making power changes so that lab personnel can take required samples within the allowable time frames. As a result, procedure changes will be made to instruct personnel on the frequency and notifications required to perform the surveillance requirements of T.S. Table 4.1-2 Item 1.h.2.



December 12, 1983
PNS-LI-83-733

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-83-19

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: NOVEMBER 12, 1983

TECHNICAL SPECIFICATION Table 4.1-2

REACTOR COOLANT SAMPLE SURVEILLANCE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over a horizontal line.

J. W. Williams, Jr.
Vice President
Nuclear Energy Department

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

4622

11

PEOPLE... SERVING PEOPLE