

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

UPDATE REPORT - PREVIOUS REPORT DATE 11/28/83

0	1	A	L	J	M	F	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35											
LICENSEE CODE															LICENSE NUMBER										LICENSE TYPE										CAT 58				

CONT

0	1	L	6	0	5	0	0	0	3	6	4	7	1	0	2	8	8	3	8	1	2	1	3	8	3	9													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34												
REPORT SOURCE															DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 2112 on 10/28/83 and 1630 on 11/3/83, the instrumentation channel associated

with flow transmitter FT-496 (Loop 3 Feed Flow) was declared inoperable due to

erroneous indication. Tech. Spec. 3.3.1 and 3.3.2, in part, require this channel

to be operable. Tech. Spec. action statement requirements were met. Health/

safety of the public was not affected.

0	9	I	A	11	X	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26										
SYSTEM CODE					CAUSE CODE					CAUSE SUBCODE					COMPONENT CODE					COMP. SUBCODE					VALVE SUBCODE				

(17) LER/NO
REPORT
NUMBEREVENT YEAR
[8] [3]SEQUENTIAL
REPORT NO.
[0] [5] [4]OCCURRENCE
CODE
[0] [3]REPORT
TYPE
[X]REVISION
NO.
[1]ACTION
TAKEN
[X] [18]FUTURE
ACTION
[Z] [19]EFFECT
ON PLANT
[Z] [20]SHUTDOWN
METHOD
[Z] [21]HOURS
[0] [0] [0] [0]ATTACHMENT
SUBMITTED
[N] [23]NPRD-4
FORM SUB.
[N] [24]PRIME COMP.
SUPPLIER
[Z] [25]COMPONENT
MANUFACTURER
[Z] [9] [9] [9]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

No cause for these events could be determined. Following satisfactory performance

of FNP-2-STP-215.5 (Main Feedwater FT-496 Loop Calibration and Functional Test

N2C22FT0496) and verification of proper indication during performance of FNP-2-

STP-1.0 (Operations Daily and Shift Surveillance Requirements), the FT-496 instru-

mentation channel was declared operable at 0150 on 10/29/83 and 0500 on 11/4/83.

1	5	F	28	0	2	1	29	NA	A	31	Operational Event								
7	8	9	10	11	12	13	14	15	16	17	18								
FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			

1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE	

1	7	0	0	0	37	Z	38	NA
7	8	9	10	11	12	13	14	15
PERSONNEL EXPOSURES NUMBER				TYPE				DESCRIPTION

1	8	0	0	0	40	NA
7	8	9	10	11	12	13
PERSONNEL INJURIES NUMBER				DESCRIPTION		

1	9	Z	42	NA
7	8	9	10	11
LOSS OF OR DAMAGE TO FACILITY TYPE				DESCRIPTION

2	0	N	44	NA
7	8	9	10	11
PUBLICATION ISSUED				DESCRIPTION

8312200479 831213
PDR ADOCK 05000364
S PDR

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156