




Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

December 16, 1983
Fort St. Vrain
Unit No. 1
P-83406



Mr. John T. Collins, Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/83-050 and Reportable Occurrence Report No. 50-267/83-051, Finals, submitted per the requirements of Technical Specification AC 7.5.2(b)2 and AC 7.5.2(b)3.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/83-050 and Reportable Occurrence Report No. 50-267/83-051.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/djm

Enclosures

cc: Director, MIPC

8312280118 831216
PDR ADOCK 05000267
S PDR

HOOS
11