



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

December 19, 1983

Director  
Office of Nuclear Reactor Regulation  
U S Nuclear Regulatory Commission  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60

Steam Generator Tube Plugging

Following recent outages on both units, per Technical Specification 4.12.E.1, the following steam generator tube plugging information is being reported.

During the September 1983 outage on Unit 2, twenty tubes were plugged. Five tubes were plugged in steam generator 21 and fifteen in steam generator 22. The percentage of tubes plugged is 0.8% and 2.4% in steam generators 21 and 22, respectively.

During the current outage on Unit 1, eighteen tubes were plugged. Ten tubes were plugged in steam generator 11 and eight tubes were plugged in steam generator 12. The percentage of tubes plugged is 1.2% and 0.3% in steam generators 11 and 12, respectively.

This information will be expanded upon in the Inservice Inspection Report for each unit. Also Tables 4.3-13 and 14 of the Prairie Island Updated Safety Analysis Report will be updated in the next revision.

If you have questions concerning this information please call.

*DMM*  
D M Musolf  
Manager - Nuclear Support Services

DMM/dab

c: NRR Project Manager, NRC  
Regional Admin-III, NRC  
Resident Inspector, NRC  
G Charnoff

*A001  
1/0*

8312300031 831219  
PDR ADOCK 05000282  
P PDR