

CONTROL BLOCK: <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																																	
01 C A S O S 3 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																																	
CON'T																																																											
01 REPORT SOURCE L 6 0 5 0 0 0 3 6 2 7 1 1 1 5 8 2 8 1 2 1 2 8 3 9										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																																	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																																																											
02 In August 1982, prior to Operating License issuance on 11/15/82, Unit 3																																																											
03 fire detection panels in Zones 1, 9, and 28 failed the 6-month Surveil-																																																											
04 lance Test S023-I-2.62. In accordance with LCO 3.3.3.7, Action State-																																																											
05 ment 'a', fire watches were established on 11/11/82, prior to Operating																																																											
06 License issuance. Fire spray/sprinkler systems remained operable.																																																											
07 Public health and safety were not affected. See LER 83-067 (Docket																																																											
08 No. 50-361).																																																											
09										SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE																																																	
09 A B 11 E 12 X 13 I N S T R U 14 E 15 Z 16										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																																	
17 LER/RO REPORT NUMBER 8 2										EVENT YEAR 8 2										SEQUENTIAL REPORT NO. 0 1 0										OCCURRENCE CODE 0 3										REPORT TYPE X										REVISION NO. 1									
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPR-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER										18 A 19 Z 20 Z 21 Z 22 0 0 0 0 23 N 24 N 25 A 26 A 1 6 1 0 5										33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50																																							
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																																																											
10 Initial testing revealed the need to replace/repair components in																																																											
11 various fire panels The replacement/repairs have been completed as of																																																											
12 9/28/83.																																																											
13																																																											
14																																																											
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)										15 B 28 0 0 0 29 NA B 31 Surveillance Test										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)										16 Z 33 Z 34 NA NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)										17 0 0 0 37 Z 38 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
PERSONNEL INJURIES NUMBER DESCRIPTION (41)										18 0 0 0 40 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)										19 Z 42 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
PUBLICITY ISSUED DESCRIPTION (45)										20 N 44 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40																																							
NAME OF PREPARER J. G. HAYNES										PHONE 714/492-7700										NRC USE ONLY																																							