

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (815) 942-2920 x489

GPO 917-926

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12 - 2 - 83 - 153				

PART 1	TITLE OF EVENT	OCCURRED	
	Failure to Pump D/W Floor Drain Sump Within Allotted Time	11/18/83	1200
	REASON FOR SUPPLEMENTAL REPORT	DATE	TIME
	Deviation number was reported instead of L.E.R. number.		
PART 2			
ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>Ja Cusla</u>	
DATE	<u>12/28/83</u>	<u>12/28/83</u>	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas D. Curt</u>		
	STATION SUPERINTENDENT	<u>12/29/83</u>	DATE



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

JMB

December 23, 1983

DJS Ltr #83-1227

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-75/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. Error was made in reporting deviation number instead of L.E.R. number.

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

JAN 4 1984

IE 22
11