

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

December 22, 1983

BLRD-50-438/82-04

BLRD-50-439/82-04

02 DEC 29 A 9:15

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BONNET STUDS IMPROPERLY TORQUED ON
DECAY HEAT REMOVAL VALVES - BLRD-50-438/82-04, BLRD-50-439/82-04 -
SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
R. V. Crlenjak on December 22, 1981 in accordance with 10 CFR 50.55(e) as
NCR 1686. This was followed by our interim reports dated January 20,
April 15, June 28, August 24, and November 1, 1982 and January 10, 1983,
and our final report dated April 13, 1983. Below is our supplemental final
report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector Paul Fredrickson on December 7, 1983,
the date of December 5, 1983 for completion of corrective actions indicated
in our final report on this matter was not met. The Division of
Construction's priorities have been reevaluated as a result of the
Bellefonte schedule reassessment program. Consequently, insufficient
manpower was assigned to this task in order to complete it by the due date.
The corrective action on this matter will be completed by
January 16, 1984.

If you have any questions concerning this matter, please get in touch with
R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

8401040339 831222
PDR ADOCK 05000438
S PDR

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

IE 27 1/0