




Public Service Company of Colorado

2420 W. 26th Avenue, Suite 100D Denver, CO 80211

January 3, 1984
Fort St. Vrain
Unit No. 1
P-84001

Mr. John T. Collins
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



SUBJECT: Submittal of Fuel Rod
Surveillance Report

REFERENCES: G-83042, P-81322, P-83058

Dear Mr. Collins:

This letter submits 40 copies of the FSV Fuel Surveillance Report, "Metallographic Examination of a Fuel Rod from Segment 2 FSV Fuel Element 1-2415", GA Technologies Doc. No. 906968. This submittal fulfills Part One of the commitments made in P-83058.

The examination found that the performance of the fuel was acceptable. There was no evidence of fuel rod-block interaction, and no kernel migration was observed.

If PSC can be of further assistance, or if you have any questions regarding this matter, please contact Mr. M.H. Holmes at (303) 571-8409.

Very truly yours,

Lamorne Brey

H. L. Brey, Manager
Nuclear Engineering Division

8401130085 840103
PDR ADOCK 05000267
P PDR

HLB/SH:pa

Attachment

Reviewed: *Stephen E. Fisher*

H005
11