

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT  
STAGE

1	6	0	5	0	0	0	3	0	5	7	1	2	0	6	8	3	0	1	0	5	8	4	9			
60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

During full power operation, the 1D containment fan coil unit was removed from service to repair service water leaks. This placed the plant in an LCO per TS 3.3.b.2.A which allows one fan coil unit to be out of service for up to seven days and is reportable per TS 6.9.2.b(2) as operation in a degraded mode permitted by an LCO. Since the other three fan coil units and the containment spray pump were in service there was no effect on public health and safety.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The leaks were caused by sand and water erosion of the return bends in the service water cooling coils. The affected bends were cut out and replaced, the cooling coils passed an inservice hydrostatic test and the fan coil unit was returned to service within TS time limits. An investigation has been initiated to study erosion problems in service water heat exchangers. No further update will be made to this LER.

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
1	2	(42)

8401130324 840105  
PDR ADOCK 05000305  
S PDR

NEC USE ONLY

PLAN DE PREPARI

S. J. Bernhardt / J. G. Thorgersen

PHONE (414) 388-2562

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

January 5, 1984

Mr. J. G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305  
Operating License DPR-43  
Reportable Occurrence 83-034/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-034/03L-0 is being submitted.

Very truly yours,

C. W. Giesler  
Vice President - Nuclear Power

JGT/jks

Attach.

cc - Dir, Office of Inspection & Enforcement  
US NRC, Washington, DC 20555  
Dir, Office of Mgt Info & Program Control  
US NRC, Washington, DC 20555  
INPO Records Center  
Suite 1500, 1100 Circle 75 Parkway  
Atlanta, GA 30339  
Mr. Robert Nelson, NRC Resident Inspector  
RR #1, Box 999, Kewaunee, WI 54216  
Mr. S. A. Varga, Chief  
US NRC, Washington, DC 20555

*FE22*  
JAN 9 1984